Aramco Written test Questions Section one, 30 Question 1 While using grinder it is important to wear both safety goggles and face shields 2 The ratio for the ladder slope is 4:1 3 The spoil should be kept 2 feet away from the excavation 4 Safety harness must be used above 1.8 meter height 5 Any excavation deeper than 1.2 meter is confined space 6 ELCB is earth leakage circuit breaker 7. GFCI is Ground fault circuit interrupter 8 GI general instruction for work permit is GI 2.100 9. GI general instruction for Man basket and crane suspended platform is GI 7.027 10 Extended outriggers is not effecting the load capacity of crane 11 Every crane must be inspected after 3 months 12 Heavy equipment's shall not be operated with in 1.8 m (6ft) of any excavation 13. Ladders or other means of access shall be provided every 7.5m (25 ft.) in all occupied excavations 14. Ladder shall be extended minimum 1 m (3 ft.) 15 Maximum Pressure of o2/Acetylene gas cylinder is 15psi 16 Cutting welding and grinding is not allowed in o2 enriched environment greater than 23.5% 17 While welding all sewers must be covered prior to work with in 23 m (75 ft) 18 Safe distance of cranes and heavy equipment from power lines are as below Up to 50000V is 3m (10ft) 50000V to 250000V is 6m (20 ft) Over 250000 V is 7.6m (25ft) 19. Maximum voltage for portable electrical hand tools shall not exceeds 125 V 20. SCBA is self-contained breathing apparatus 21 Three types of Scaffolds tags in Aramco

C. Green, Scaffold passed inspection

B, Yellow, Full body harness required

A, Red. Do not use scaffold

- 22. Maximum allowable slopes for less than 6 m (20ft) deep for C type soil is 34 degree
- 23. A dead power line fall on the crane. In this situation crane operator should remain calm and don't fled away from the crane until the emergency help arrives
- 24. Most loose/unstable soil type is C TYPE
- 25. Most common type of fire in the construction are A, B & C fire
- 26. While selecting the Location and quantity of Foam fire extinguisher in any location must consider the severity of fire (How much it worst be)
- 27. The U Clamp must be installed 3 on both dead end

Note: Passing Percentage for HSE Officer is 70% (21 Question) and for HSE Supervisor is 80 % (25 Question)

Section ii

(Incident report)

Incident Scenario: Fire location is Fabrication shop, Khurais Fabrication yard, Time 1:30 pm, date Oct 25, 2015, injured one person

- 1, Describe the incident
- 2 What was the cause of incident?
- 3, immediate corrective action
- 4. Recommendations

Section III

Prepare the JSA of your own choice or JSA activity may be informed by Examiner